



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
November 1, 2005

Supervisor 1027

Mine Name: Bright 1 & 2
Operator Name: 3-H Landscape Products LLC
2160 East Riverside Drive
St. George, Utah 84790

Permit number: M/021/030
Inspection Date: October 27, 2005
Time: 2:10 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Active

Weather: Cool, Windy

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

I wanted to check the extent of mining activity at this site since my last site inspection on 11/15/2004.

Directions to Site:

Please refer to previous inspection reports for directions to the site.

Inspection Summary:

Three of the four quarries at the site appear to have been the focus of most of the mining activities. There appears to have been limited mining in the south quarry, which remains small. Most of the mining activity seems to have been confined to the north and center quarry. The soil above the north quarry highwall has been stripped in anticipation of further mining. A ~25' highwall has been developed in the north quarry and mining has enlarged the center hilltop quarry. There were product piles located both in the center and north quarry areas.

At the time of the this inspection all of the mining and screening equipment was located in the storage area at the center quarry.


Inspection Date;; Report Date:
Page 2 of 2
M/021/030

The site had been GPS'd previously by Ed Ginouves (BLM) and a combined total of 13.96 acres of disturbance was noted.

Conclusions and Recommendations:

All of the quarries located in this permit were clean and appear to be well run. I noted no environmental or erosion problems at any of the sites.

Inspector's Signature



Date: November 1, 2005

dj:jb

cc: 3-H Landscape Products LLC, Operator
Ed Ginouves, BLM, Cedar City FO (UTU-77247-A2)

Attachment: GPS
O:\M021-Iron\M0210030-Bright1&2\Inspections\10272005insp.doc

Mine Number: M0210030
Mine Name: Bright 1 and 2
Township 35 S Range 17 W Section 21-22-27-28 SLBM

Inspection Date Oct. 05, 2005
Map Produced by DKS

Acres Disturbed	13.96
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0
Total Acres Disturbed	13.96

Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
All items symbolized in legend may not be appear on map

County Boundary

Township or range line: location doubtful

Access

Mine

NonMine

Other

Interstate

US Route

State Route

Primary Route

Secondary Route

Main Dirt Road

Unimproved Road

Interchange

Trail

Bond Area

SITLA Mineral Leases

BLMSaltMinerals

CommunityPit

Township or range line: location doubtful

Section line

Section line: location doubtful

Disturbed

Regraded

Seeded

Released

Excluded

PreExisting

Prelaw


Bond Area

SITLA Mineral Leases

BLMSaltMinerals

CommunityPit

DOQ imagery date 2004



1:7,500 1 inch equals 625 feet
Verify Scale

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program